

MarcellusGas.Org

Document Disclaimer

The information contained in this document represents content obtained from the Pennsylvania Department of Environmental Protection. MarcellusGas.Org makes no claims whatsoever as to the accuracy, timeliness, or completeness of the information provided.

By downloading this document, you agree that you have accepted the terms and conditions set forth in the MarcellusGas.Org User Agreement located at:

http://www.marcellusgas.org/terms_of_use.php



Pennsylvania Department of Environmental Protection

230 Chestnut Street
Meadville, PA 16335-3481
April 2, 2009

Northwest Regional Office

814-332-6942
Fax: 814-332-6121



Re: Complaint ID 261105
Act 223 Section 208 Determination
Oliver Township, Jefferson County

Dear [REDACTED]

Our investigation of your area on February 24, 2009, confirmed that Dominion Exploration and Production, Inc. was responsible for affecting your water supply well. They have addressed issues concerning elevated iron in your water by placing a treatment system on your water supply. The quality degradation was shown by comparing predrilling and postdrilling analyses taken at your water well by Environmental Service Labs, Inc., who was contracted by you. This predrilling analysis was taken in relation to the drilling of gas well [REDACTED]. At this time, Dominion is continuing to address issues of apparent diminished quantity in your water supply by considering remedial options. The Department will be taking samples in the future to determine if the treatment system in place will be adequate to treat the water to predrill quality. This replacement is proceeding as is described in the Oil & Gas Act 223, Section 208.

I have enclosed two sample analyses, as well as an interpretation fact sheet. Thank you for your patience. I will be in contact with you. Please contact me if you have any questions.

Sincerely,

Christine Miner, P.G.
Licensed Professional Geologist
Oil & Gas Management

Enclosures

cc: Doug Neely
Christine Miner
File

CM:kab